

ARMY RESEARCH LABORATORY




Correlation of the Failure Modulus to Fracture-Generated Surface Area in Uniaxially Compressed M43 Gun Propellant

Robert J. Lieb

ARL-TR-884

October 1995

19951130 071



DTIC QUALITY INSPECTED 5

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION IS UNLIMITED.

NOTICES

Destroy this report when it is no longer needed. DO NOT return it to the originator.

Additional copies of this report may be obtained from the National Technical Information Service, U.S. Department of Commerce, 5285 Port Royal Road, Springfield, VA 22161.

The findings of this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

The use of trade names or manufacturers' names in this report does not constitute indorsement of any commercial product.

REPORT DOCUMENTATION PAGE

Form Approved
OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project(0704-0188), Washington, DC 20503.

1. AGENCY USE ONLY (Leave blank)		2. REPORT DATE October 1995	3. REPORT TYPE AND DATES COVERED Final, Jun 94 - Apr 95
4. TITLE AND SUBTITLE Correlation of the Failure Modulus to Fracture-Generated Surface Area in Uniaxially Compressed M43 Gun Propellant			5. FUNDING NUMBERS 1L162618AH80
6. AUTHOR(S) Robert J. Lieb			
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Army Research Laboratory ATTN: AMSRL-WT-PD Aberdeen Proving Ground, MD 21005-5066			8. PERFORMING ORGANIZATION REPORT NUMBER ARL-TR-884
9. SPONSORING/MONITORING AGENCY NAMES(S) AND ADDRESS(ES)			10. SPONSORING/MONITORING AGENCY REPORT NUMBER
11. SUPPLEMENTARY NOTES			
12a. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution is unlimited.			12b. DISTRIBUTION CODE
13. ABSTRACT (Maximum 200 words) M43, a large-caliber, nitramine composite propellant, was tested in uniaxial compression at a rate of 100/s to 50.0% strain at temperatures from -40° to 60° C. Similar tests were performed to 20.0 and 10.0% strain. Failure modulus values (defined below) were measured and sufficient propellant was damaged so that closed bomb firings could be performed, which determined how the grain damage affected the pressure generation at ballistic pressures. After the burning rate was established using undamaged grains, the pressure-time curves from the damaged propellant were analyzed to extract the burning surface area profiles using the analysis program BRLCB. Results showed that the intercept of the linear fitted profile on the surface area axis, which was determined by plotting surface area against the amount of the propellant charge burned and fitting the initial 10% of that curve to a least squares fit straight line, seemed to be directly related to the logarithm of the failure modulus and the end strain. The resulting three curves, one for each level of strain, fell into a series that permitted the initial effective surface area to be predicted for any combination of failure modulus and the strain level within the fracture domain. These results seem to provide a method for assessing fracture damage by means of a simple mechanical measurement.			
14. SUBJECT TERMS fracture, gun propellant, M43, failure			15. NUMBER OF PAGES 25
			16. PRICE CODE
17. SECURITY CLASSIFICATION OF REPORT UNCLASSIFIED	18. SECURITY CLASSIFICATION OF THIS PAGE UNCLASSIFIED	19. SECURITY CLASSIFICATION OF ABSTRACT UNCLASSIFIED	20. LIMITATION OF ABSTRACT SAR

Intentionally Left Blank

ACKNOWLEDGMENT

The author would like to especially thank Mr. Michael G. Leadore, who performed the mechanical property measurements and conducted the closed bomb experiments for this report. His skill and dedication to excellence made it possible to draw meaningful conclusions from the measurements. Without his efforts, this report could not have been written.

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A-1	

Intentionally Left Blank

TABLE OF CONTENTS

	<u>Page</u>
ACKNOWLEDGMENT	iii
LIST OF FIGURES	vii
LIST OF TABLES	vii
1. INTRODUCTION	1
2. EXPERIMENTAL PROCEDURE	1
2.1 Mechanical Response Measurement	1
2.2 Fracture-Generated Surface Area Measurements	3
2.3 Details of the Experiment	3
3. RESULTS	3
4. ANALYSIS	6
4.1 Method of Analysis	6
4.2 Results of Analysis	6
5. DISCUSSION	10
6. CONCLUSIONS	11
7. FUTURE STUDIES	11
8. REFERENCES	12
DISTRIBUTION LIST	13

Intentionally Left Blank

LIST OF FIGURES

<u>Figure</u>	<u>Page</u>
1 Servohydraulic Tester	2
2 Mechanical Characterization Parameters	2
3 Stress versus Strain Response Curves for M43 from which Failure Modulus Values are Determined	4
4 Ln of the Failure Modulus of M43 Propellant versus Temperature over the Temperature Range of Ballistic Interest.....	4
5 Photographs of the M43 & M30 Propellant Specimens after Compression to 50% Strain	5
6 Theoretical and Undamaged Values of the Surface Area Ratio versus Fraction Burned for the 19-Perforation M43 Grains	5
7 Surface Area Profiles for Propellant Damaged at 50% Strain	5
8 Original and Interpolated S/S_0 versus Fraction Burned Curves with Corresponding Characterization Parameters	7
9 Average Least-Squares-Fit Parameter versus Ln of the Failure Modulus for S/S_0 versus Fraction Burned at Each End Strain	7
10 S_i/S_0 Intercept Parameters from Figure 8a versus End Strain	8
11 The S_i/S_0 Surface from Equations 1 & 2	9

LIST OF TABLES

<u>Table</u>	<u>Page</u>
1 Nominal Percent Composition of M43	2
2 Mechanical Response Parameters	4
3 Average Values of Failure and Surface Area Ratio Parameters	7

Intentionally Left Blank

1. INTRODUCTION

Attempts to link the relationship between mechanical response measurements and gun performance have made progress in the past 8 years.¹⁻¹² Early work revealed that conventional mechanical parameters did not relate well to fracture susceptibility. The search for a simple mechanical parameter that could measure the propensity for a propellant to generate surface area upon mechanical failure resulted in the development of a failure parameter called the failure modulus,³ E_f , that measures the rate at which the material strength is lost as a function of strain after material failure has begun. This parameter has been used as a guide in the development of new propellants to ensure that improvements in formulation and processing did not degrade the mechanical response characteristics of the material, which could result in poor performance and increased vulnerability response. It has also been successfully used to evaluate the relative fracture susceptibility among various propellant lots, or between unconditioned propellant and propellant that has been subjected to special conditioning that may affect its mechanical response, e.g., thermal cycling.

The failure modulus showed indications of direct usefulness when the changes of the vulnerability response related directly to changes measured in this parameter.² A correlation was found for propellant beds at low temperature subject to a shaped charge jet attack and led to other studies that attempted to make the correlation more direct. However, the relationship was made between *changes* in both responses, rather than directly relating the responses themselves. Most recently, a direct link between this failure parameter and a measure of the amount of fracture-generated surface area produced when M30 propellant was uniaxially compressed.¹² The failure modulus was measured and enough grains were damaged so that closed bomb firings could be performed to determine how the grain damage affected the pressure generation. A small (21 cc) closed bomb was used so that large numbers of grains did not have to be damaged to reach gun-like pressures in the closed vessel. After the burning rate was established using undamaged grains, the pressure-time curves from damaged propellant were analyzed for surface area, which produced a profile in the form of the surface area versus fraction of the charge burned. Analyzing these results showed that the intercept of the profile curve on the surface area axis, derived by fitting the initial 10% of the curve to a least squares fit straight line, was directly related to the logarithm of the failure modulus. The three resulting curves, one for each level of strain, fell into a series that permitted the effective surface area profile to be predicted for any combination of failure modulus and the strain level within the fracture domain. These results provided a method for assessing fracture damage for the M30 propellant by means of a simple mechanical measurement. In this study, the same procedure was applied to the nitramine composite propellant, M43.

2. EXPERIMENTAL PROCEDURE

2.1 Mechanical Response Measurement

The propellant response was measured using a specially designed servohydraulic tester,⁴ illustrated in Figure 1. The machine allows for compression measurements to be performed at rates as great as 1000 s^{-1} for a specimen with a nominal length of 1 cm. Compression is arrested when contact occurs between the impact bell and cone. Therefore, the amount of specimen compression can be accurately predetermined by setting the anvil height. This contact between bell and cone not only stops the specimen compression, but it also shunts the force around the specimen. The nitrogen spring absorbs the mechanical energy and moderates the deceleration rate of the massive ram. The

force applied to the specimen is measured using the gauge inside the impact bell. During compressive response measurements, displacement is measured with a linear variable differential transformer in the actuator column and is corrected for machine stiffness.

The specimens were prepared from multiperforated M43 gun propellant grains whose formulation is listed in Table 1. The specimen preparation procedure began by cutting the sample with a diamond saw to a length of 1.00 cm. The ends were cut flat, parallel and perpendicular to the grain axis according to the specifications in an updated version of the test entitled "Uniaxial Compressive Gun Propellant Test".¹³ Temperature conditioning was achieved by placing prepared grains inside the environmental chamber for a time at least twice that needed to reach thermal equilibrium (a total of 30 minutes). The specimen was then placed on the anvil and compressed. This testing took place within the conditioning chamber, so no transfer was required and, therefore, no thermal disruption occurred.

The final strain to which the specimen was taken is determined by the distance between the anvil and the force gauge when the bell and cone surfaces are mated. That distance was determined by placing a lead specimen on the anvil and performing a compression. This allowed for any dynamic affects to be taken into account that may have been overlooked in a static measurement. The percentage strain used in these tests was selected to be 50, 20, and 10%. From previous testing, it is known that failure of the grain occurs between 2 to 4% strain, depending upon strain rate and temperature.

The parameters measured in a response characterization test are the modulus (E), maximum stress (σ_m), strain at maximum stress (ϵ_m), stress at failure (σ_f), strain at failure (ϵ_f), and failure modulus (E_f). The definitions of these parameters are illustrated in Figure 2. The failure modulus is the slope of the stress-strain curve in the near-linear region between strain at maximum stress and twice that value. If no maximum stress occurs in the region of failure, the failure modulus is measured between the strain at

Table 1. Nominal Percent Composition of M43

Component	Percent Composition
Nitrocellulose (NC)	4
NC Nitration Level	12.6
RDX (Ground))	76
Cellulose Acetate Butyrate	12
Plasticizer	8




Figure 1. Servohydraulic Tester




Figure 2. Mechanical Characterization Parameters

failure and three times that value. Measurement of the failure modulus was made at -40, -20, 0, 20, 40, and 60° C, and the reported values were determined from the average curve generated from five response curves, except in the -40° C case. At -40° C, the response of M43 was extremely brittle and failure occurred over a wide range of strain, which caused the average curve to be much less meaningful. At this temperature, therefore, the parameters listed were determined for the individual response curve and were then averaged. The specimen strain rate was chosen to be 100 s⁻¹, which is the order of strain rate encountered by the grains during a ballistic firing.

2.2 Fracture Generated Surface Area Measurement

The grains, damaged by uniaxial compression as outlined above, were burned in a mini-closed bomb (MCB) to determine the effect that the mechanical damage had on the pressure generation of the propellant. The MCB is a special, small-volume closed bomb.⁵ The rate of pressurization during combustion is controlled by the intrinsic burning rate of the propellant and the surface area exposed to the flame. Since M43 is a low-vulnerability propellant and sometimes is difficult to ignite, 0.1 g of black powder was used as an ignition aid. After the propellant was burned and the resulting pressure-time curves acquired, the evolving surface area of the charge could be determined using the established burning rate of the propellant.

Undamaged specimens were burned in the MCB at the same loading density that was used in the damaged grain firings. These pressure-time traces were analyzed using the closed bomb reduction code BRLCB¹⁴ to establish the burning rates for the M43 propellant for these tests. Once established, the surface area from all the pressure-time histories can be determined using the same code. The output from the code provides pressure in MPa and the corresponding surface area in square centimeters. This output was converted to intrinsic parameters of fraction burned and surface area ratio (S/S_0), by dividing the pressure by the maximum pressure and the surface area by the initial surface area of the undamaged grain (S_0), respectively. This allowed closed bomb runs with different charge masses, and corresponding pressure differences, etc., to be compared.

2.3 Details of the Experiment

Enough grains were damaged to provide two closed bomb firings for each temperature-strain condition. The initial series of tests done with M30 propellant¹² showed that two closed bomb firings could be performed with reasonable assurance of agreement. If the results from the two identically damaged propellant charges varied significantly, subsequent closed bomb tests were performed to resolve the differences. With six temperatures and three end strain conditions, a total of 45 closed bomb tests was conducted. This included some instances in which more than two firings were performed to verify the repeatability of the process.

3. RESULTS

The uniaxial compressive mechanical response of M43 propellant is shown in the stress versus strain curves presented in Figure 3. From these curves, the failure modulus is calculated as outlined above. Results of some mechanical property measurements are shown in Table 2. Figure 4 shows the natural log of the failure modulus plotted against temperature and indicates the nature of the response. These plots indicate that fracture *very rapidly* becomes more significant at lower temperatures. This is also reflected by the physical appearance of the grains after testing. Figure 5

shows typical 50% strain specimens after uniaxial compression. Figure 5c is included for comparison. It shows how M30 maintains greater integrity and shows the reduced level of fracture when damaged under the same conditions as M43 propellant. The failure modulus values reflect the increase in fracture observed in the tested specimens, but more importantly, the magnitude of E_f quantifies the extent of the fracture.

For each closed bomb firing, a surface area ratio versus fraction burned plot was obtained, as described above, which reflected the amount of surface area available to the flame throughout the propellant combustion. Figure 6 shows the theoretical and typical experimental values for the surface area ratio versus fraction burned for undamaged grains. Note that as the 19-perforated grains burn the surface area increases. This is due to the nature of the progressive grain design. This area profile is required to provide the gun with its designed performance. Any deviation from this profile reduces performance and in cases of severe deviation, can produce chamber pressure waves that can lead to catastrophic gun failure. The surface area profiles shown in Figure 7 are for grains damaged to 50% end strain at three temperatures. These deviations from the profile required for efficient gun firing are much more severe than those observed for M30 propellant¹² by about a factor of 3 and extend for much greater fraction burned. If the M43 surface area profiles observed here were present during a large caliber gun firing, large pressure variations would be present within the gun. The profiles for these damaged grains were analyzed using the procedure outlined below.

4. ANALYSIS

4.1 Method of Analysis

Many attempts were made in the previous study¹² with M30 propellant to associate the surface area curves obtained from the closed bomb results to the failure modulus: curve aver-

Table 2. Mechanical Response Parameters

T (° C)	Stress at Failure (MPa)	Strain at Failure (%)	Modulus (GPa)	Failure Modulus (GPa)
-40	122	2.75	5.97	-18.40
-20	140	3.40	5.28	-12.50
0	124	3.25	5.53	-1.58
21	92	3.01	4.30	-0.43
40	65	2.87	2.95	-0.27
60	52	2.56	2.59	-0.19




Figure 3. Stress versus Strain Curves for M43 from which Failure Modulus Values are Determined




Figure 4. Ln of the Failure Modulus of M43 Propellant versus Temperature over the Temperature Range of Ballistic Interest




Figure 5. Photographs of the M43 & M30 Propellant Specimens after Compression to 50% Strain




Figure 6. Theoretical and Undamaged Values of the Surface Area Ratio versus Fraction Burned for the 19-Perforation M43 Grains




Figure 7. Surface Area Profiles for M43 Propellant Damaged at 50% Strain

aging, a comparison of areas under curves to a certain fraction burned, shifting of curves to match minimum surface area values, primary and secondary S/S_0 curve intercepts, and several other methods. The method that seemed to best characterize the deviation reflected in the curves and was still simple enough to be applied easily is described below.

The initial amount of surface area (S_i) available to the flame and the evolution of that surface area are both very important to the pressure generation rate during the early portion of the ballistic cycle. It would be desirable to incorporate into a set of numbers a measure of mass (pressure) generation deviation that can be expected due to fracture damage. To date, the method that best exhibits this information for the conditions thus far examined is to fit the points of the S/S_0 versus fraction burned curve, to 10% fraction burned, to a least squares fit. The intercept of this line (S_i/S_0) and its slope (M) characterize the important features mentioned above. The intercept indicates the initial surface area due to fracture, and the slope indicates the evolution of the area as the charge burns. (Three such lines are shown in Figure 7.) There are several reasons why this approach reflects critical aspects of mass generation within the gun. First, the conditions that result in significant deviations from planned mass generation within the gun are established very early in the ballistic cycle. Thus, it makes sense to use only the information contained in the early burning of the charge, i.e., the first 10%. If surface area variances begin to occur later in the cycle, the performance will be affected, but the chamber volume has increased significantly (and is continuing to rapidly expand), so that excess pressurization is more difficult to generate and pressure variations are likely to be less severe than those occurring at much smaller chamber volumes. Next, this method uses more than a few initial points to determine the value of the parameters being used to characterize the increased surface area. Those familiar with closed bomb analysis know that the most uncertain values generated in the process are those obtained at low fraction burned. This method of curve fitting eliminates the dependence of the value obtained from a few points in early, uncertain region, while still using values in this early combustion region to influence the parameter value. And lastly, by incorporating the points at higher fraction burned, i.e., to 10%, a measure of how the fracture generated surface area is evolving can be determined.

4.2 Results of Analysis

The above analysis procedure was applied to each of the closed bomb data sets. The intercept (S_i/S_0) of the linear least squares fit of S/S_0 versus fraction burned curve between the maximum value of S/S_0 and the value of S/S_0 at 10% fraction burned was obtained for the average curve for each end strain and temperature condition. To provide equal weight to each portion of the curve between the points being fit, values of S/S_0 were calculated at equal intervals of fraction burned, i.e., $\Delta FB = 0.002$, based on a linear interpolation between data points. This was necessary because high S/S_0 values cause more propellant to be consumed per unit time. Since data are recorded at equal time intervals, the representation of the data by intervals of fraction burned resulted in larger intervals between data points for higher values of S/S_0 . Since greater levels of propellant damage result in higher initial values of S/S_0 , for severely fractured grains, there was a significantly lower density of data points at higher values of S/S_0 . This lower point density can skew the fitted curve by affecting the intercept and slope, as can be seen in Figure 8. The linear interpolation procedure described above was employed to make the derived parameters more sensitive to fracture damage. The average values derived from this procedure appear in Table 3 along with the corresponding values of the failure modulus.

Table 3. Average Values of Failure and Surface Area Ratio Parameters

Temperature (° C)	E_f (GPa)	$\ln(-E_f)$	Average Intercept (S_f/S_0)			Average Slope (M)		
			50%	20%	10%	50%	20%	10%
60.0	-0.19	-1.655	52.9	9.74	-	-500	-102	-
40.0	-0.27	-1.295	58.9	7.92	-	-352	-68.6	-
20.0	-0.43	-0.837	60.9	23.4	-	-220	-249	-
0.0	-1.58	0.457	78.1	43.7	19.8	-591	-401	-231
-20.0	-12.50	2.526	92.4	46.3	27.5	-450	-560	-305
-40.0	-18.40	2.912	106.5	61.6	24.5	-351	-509	-296






Figure 8. Original and Interpolated S/S_0 versus Fraction Burned Curves with Corresponding Characterization Parameters

If these intercept values are plotted against the logarithm of the failure modulus for each of the end strain levels and a linear least squares fit is made to the points, the plots in Figure 9 result. Plots similar to those in Figure 9 were generated for M30 propellant,¹² and resulted in linear relationships being demonstrated between both the intercepts and slope values of the lines and the end strain values of each line. This permitted characterization of the initial surface area and its evolution over the first 10% of fraction burned in terms of the end strain, the failure modulus, and the fraction burned. This same relationship is only partially realized for M43 propellant. If the fitting parameters from the straight lines in Fig-



a. Average Surface Area Ratio Intercept



b. Coefficient of Fraction Burned (Slope)

Figure 9. Average Least Squares Fit Parameter versus Ln of the Failure Modulus for S/S_0 versus Fraction Burned at Each End Strain

ure 9a are plotted against end strain, the fitting *constants* show a linear dependence with end strain, as shown in Figure 10a. However, a plot of the fitting *slopes* of the lines in Figure 9a versus end strain show that the relation does not appear linear but seems to be more plateau-like. The curve runs from 2.52 at 10% end strain to a value of 10.5 somewhere between 10 and 20% end strain and then remains at that level. This implies that at higher end strain levels (somewhere between 10 and 20%) the rate of initial surface area increase with $\ln(-E_f)$ becomes constant. This is consistent with the mechanical response curves, shown in Figure 3, which show that for curves with a lower failure modulus value (below -1.00), the material has no strength above 20% strain. This implies that almost all the damage done to the propellant under those conditions occurred before 20% strain and that very little additional damage is done afterward. If the equations in Figure 10 are substituted into the relationships shown in Figure 9a, the S_i/S_0 versus fraction burned curve intercept can be represented in the general form $y = [\text{intercept}] + [\text{slope}] \ln(E_f)$

for $10\% \leq \epsilon \leq 20\%$, by

$$S_i/S_0(\epsilon, E_f) = [3.9769 + 1.3336 \epsilon] + [-5.36 + 0.788 \epsilon] \ln(-E_f); \quad (1)$$

and for $\epsilon > 20\%$, by

$$S_i/S_0(\epsilon, E_f) = [3.9769 + 1.3336 \epsilon] + [10.27 + 0.007\epsilon] \ln(-E_f). \quad (2)$$

These relationships can be used to predict values of effective initial fracture-generated surface area, given the measured failure modulus, and the end strain. Figure 11 shows a plot of these equations.

As mentioned above, a similar result was obtained for the slope of the line that is fit to the average S_i/S_0 versus fraction burned curves for M30. The values of average slope for M43 appear in Table 3 and are plotted against $\ln(-E_f)$ in Figure 9b. Again, the 10% and 20% data are compatible with a linear dependence with $\ln(-E_f)$. Least squares best fits can be performed on these points to characterize the evolution of the surface area as a function of fraction burned, but only to about 20% end strain. As can be seen for the 50% end strain, the points are very scattered and no linear correlation with $\ln(-E_f)$




Figure 10. S_i/S_0 Intercept Parameters from Figure 9a versus End Strain




Figure 11. The S_i/S_0 Surface from Equations 1 & 2

exists. In the case of M30, the evolution of the curve was characterized by increasing initial surface area with lower values of E_f and higher strains. As the charge burned, the further the initial value was from the original programmed value, the more rapidly the surface area attempted to return to the programmed surface area value. This result implies that there was still *some* memory in the damaged structure of the programmed value of the grain. For M43, somewhere above 20% strain it seems as if the evolution of surface area has lost most of its dependence on the initial structure of the propellant grain. This situation results in unstable evolution of S/S_0 and can lead to erratic mass generation processes similar to conventional bulk-loaded liquid propellant combustion, where the evolution of effective surface area can sometimes be very erratic. However, when the same operation is performed on the constants and coefficients of the equations of the lines found in Figure 9b, for 20% end strain and lower, the coefficient of the effective surface area curve can be approximated, as above, by placing the appropriate end strain and failure modulus values in the following equation: for $10\% \leq \epsilon \leq 20\%$,

$$\text{Slope}(\epsilon, E_f) = [-159 - 6.05 \epsilon] + [41.2 - 7.07 \epsilon] \ln(-E_f); \quad (3)$$

for $\epsilon > 20\%$ end strain, the evolution of the surface area profile seems to be erratic.

These equations can be combined to produce the effective surface area profile versus fraction burned (usually designated as Z) for the first 10% of the fraction burned for some of the conditions studied here.

For an end strain between 10 and 20%,

$$\begin{aligned} S/S_0 (\epsilon, E_f, Z) &= S_i/S_0 (\epsilon, E_f) + \text{Slope} (\epsilon, E_f) Z \\ &= [3.9769 + 1.3336 \epsilon + (-5.36 + 0.788 \epsilon) \ln (-E_f)] + [-159 - 6.05 \epsilon \\ &\quad + (41.2 - 7.07 \epsilon) \ln (-E_f)] Z. \end{aligned} \quad (4)$$

For end strains greater than 20%, the initial surface area ratio can be given by

$$S_i/S_0 (\epsilon, E_f) = [3.9769 + 1.3336 \epsilon] + [10.27 + 0.007\epsilon] \ln (-E_f), \quad (5)$$

with the surface area evolution somewhat erratic.

The domain over which these relationships can be expected to apply is somewhat unclear. Since it is unknown exactly at what end strain the plateau edge begins in Figure 10b and at exactly what end strain above 20% the evolution of surface area becomes erratic (Figure 9b), the equations presented have made assumptions that the end strain for both of these boundaries is about 20%. In any case, the value of strain must be above 10% to use these equations.

5. DISCUSSION

The above equations can be used for several purposes. As stated, if the stress state of the propellant grain is known and the failure modulus has been measured, then the effect of the initial surface area can be evaluated. The effects of the augmented surface area on combustion for the first 10% of fraction burned can be evaluated by using Equation 4 to predict an effective surface area profile during the early combustion as long as the end strain conditions are not violated. The prediction may not, however, show the dynamic effects of the surface area evolution that could affect the generation and propagation of pressure waves within the gun chamber, e.g., the enhancement of combustibility resulting from freshly fractured surfaces, but it should, nonetheless, provide a more accurate assessment of the dynamic pressures.

These equations could also be used to predict conditions in which fracture-generated surface may become a significant problem. The time-temperature equivalence of M43 and other propellants has been established⁹ over the temperature range of ballistic interest and has been related to the strain rate for more than four orders of magnitude.¹⁰ Using this information, the strain state of a propellant can be predicted for a certain strain rate deformation, at a particular temperature. In the referenced studies, it was shown that the time-temperature equivalency could be extended to predict the failure modulus, as well. This allows for an estimation of the degree of damage and its effect on combustion for a wide variety of conditions, even those outside the area of available physical measurement. If ballistic codes are used to show when certain surface area profiles subject a system to unacceptable performance, these equations can be used with the appropriate mechanical response parameters to predict when and where these conditions are likely to arise.

Other uses will become evident as the application or problem becomes more well defined. For a long time, the modeling community has had to rely on relatively arbitrary surface area augmentation algorithms. Now, for both M30 and M43, a method is available that relates a relatively easily determined mechanical parameter to a surface area profile during the early phase of combustion.

6. CONCLUSIONS

A correlation has been established that relates the end strain state of uniaxially compressed M43 gun propellant grains to a surface area profile that characterizes fracture-generated surface area during early combustion. This correlation is based on an easily measured mechanical parameter called the failure modulus. This parameter, shown in an earlier study to predict fracture surface area profiles for damaged M30 propellant,¹² has been shown to predict the initial surface area ratio for grains tested to 50% strain over a temperature range of -40° C to 60° C. In addition, the evolution of that surface area has been characterized for grains undergoing compression to levels as high as 20%. Between 20 and 50% compression, the evolution of the fracture surface area was measured to be erratic. This may be the result of the extremely brittle nature of the response that produces very large S/S_0 values and causes the loss of load-bearing ability of the material. The damage being done to the grain is thereby done at an unknown strain level.

The effective surface area profile during early combustion has been related to the logarithm of the failure modulus for each of the end strain conditions tested, and the parameters determined in these linear correlations (the constant and coefficient of each relationship) have been shown to be linear functions of the strain. The result of this is a method by which an equivalent surface area profile can be generated, based on the level of strain and the established failure modulus, that has wide application in the modeling and propellant development communities.

7. FUTURE STUDIES

This is the second propellant type to undergo this series of tests. Tests are currently under way to characterize single (M14) and double (JA2) base propellants. Initial results from these studies indicate that the level of fracture surface area generated in both of these propellant types is significantly lower than for M30 tested under similar conditions, which would make them very much less fracture susceptible than M43. While these results were qualitatively known, the assignment of specific surface area values as a function of simply measured parameters is a great aid in predicting changes in performance due to fracture generation. Also, in this current study, to clarify the domain over which the stated equations are valid, additional tests at selected end strain levels will be required. This added information, along with the time-temperature equivalency established for each of these groups, should provide a valuable tool to predict the augmentation of pressure generation attributable to fracture damage in ballistic systems.

8. REFERENCES

1. G. A. Gazonas, A. Juhasz, and J. C. Ford, "Strain Rate Insensitivity of Damaged-Induced Surface Area in M30 and JA2 Gun Propellants," Technical Report BRL-TR-3251, USA Ballistic Research Laboratory, Aberdeen Proving Ground, Maryland, August 1991.

2. P. Lu, B. Strauss, S. Moy, and R. Lieb. "Shaped Charge Jet Impact on Gun Propellants Study I - Temperature and Mechanical Properties Effects," 1991 Propulsion System Hazards Subcommittee Meeting, March 1991.
3. R. J. Lieb, and M. G. Leadore, "Mechanical Failure Parameters in Gun Propellants," Technical Report BRL-TR-3296, USA Ballistic Research Laboratory, Aberdeen Proving Ground, Maryland, November 1991.
4. G.A.Gazonas, "The Mechanical Response of M30, XM39, and JA2 Propellants at Strain Rates from 10^{-2} to 250 s^{-1} ," Technical Report BRL-TR-3181, USA Ballistic Research Laboratory, Aberdeen Proving Ground, Maryland, January 1991.
5. R. J. Lieb, "Impact-Generated Surface Area in Gun Propellants," Technical Report BRL-TR-2946, USA Ballistic Research Laboratory, Aberdeen Proving Ground, Maryland, November 1988.
6. R. J. Lieb, "The Mechanical Response of M30, JA2 and XM39 Gun Propellants to High Rate Deformation," Technical Report BRL-TR-3023, USA Ballistic Research Laboratory, Aberdeen Proving Ground, Maryland, August 1989.
7. R. J. Lieb, "High Strain Rate Response of Gun Propellant Using the Hopkinson Split Bar," Technical Report BRL-TR-3200, USA Ballistic Research Laboratory, Aberdeen Proving Ground, Maryland, February 1991.
8. L. Varga, and F. Beaupre, "Temperature, Aging and Extrusion Pressure Effects on Mechanical Properties of LOVA Gun Propellants," Technical Report, DREV Memorandum 3072/92, Defence Research Establishment, Valcartier, Quebec, June 1992.
9. R. J. Lieb, and M. G. Leadore, "Time-Temperature Shift Factors for Gun Propellants," Technical Report ARL-TR-131, Army Research Laboratory, Aberdeen Proving Ground, Maryland, May 1993.
10. R. J. Lieb, and M. G. Leadore, "Mechanical Response Comparison of Gun Propellants Evaluated under Equivalent Time-Temperature Conditions," Technical Report ARL-TR-228, Army Research Laboratory, Aberdeen Proving Ground, Maryland, September 1993.
11. R. J. Lieb, and S. F. Trevino, "Onset and Nature of Fracture of Uniaxially Compressed Gun Propellants, A Small-Angle Neutron and X-Ray Scattering Study," Technical Report ARL-TR-185, Army Research Laboratory, Aberdeen Proving Ground, Maryland, August 1993.
12. R. J. Lieb, and M. G. Leadore, "Correlation of the Failure Modulus to Fracture-Generated Surface Area in Uniaxially Compressed M30 Gun Propellant," Technical Report ARL-TR-307, Army Research Laboratory, Aberdeen Proving Ground, Maryland, November 1993.
13. Hoffman, H.J., ed., "Uniaxial Compressive Gun Propellant Test," November, 1987, *Solid Propellant Mechanical Behavior Manual*, Section 4.6.4.1, CPIA Publication 21, Johns Hopkins University, Chemical Propulsion Information Agency, Columbia, Maryland.
14. W. F. Oberle, and D. E. Kooker, "BRLCB: A Closed-Chamber Data Analysis Program, Part I - Theory and User's Manual," Technical Report ARL-TR-36, Army Research Laboratory, Aberdeen Proving Ground, Maryland, January 1993.

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
2	DEFENSE TECHNICAL INFO CTR ATTN DTIC DDA 8725 JOHN J KINGMAN RD STE 0944 FT BELVOIR VA 22060-6218
1	DIRECTOR US ARMY RESEARCH LAB ATTN AMSRL OP SD TA 2800 POWDER MILL RD ADELPHI MD 20783-1145
3	DIRECTOR US ARMY RESEARCH LAB ATTN AMSRL OP SD TL 2800 POWDER MILL RD ADELPHI MD 20783-1145
1	DIRECTOR US ARMY RESEARCH LAB ATTN AMSRL OP SD TP 2800 POWDER MILL RD ADELPHI MD 20783-1145
	<u>ABERDEEN PROVING GROUND</u>
5	DIR USARL ATTN AMSRL OP AP L (305)

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	HQDA ATTN SARD TR MS K KOMINOS PENTAGON WASHINGTON DC 201310-0103
1	HQDA ATTN SARD TR DR R CHAIT PENTAGON WASHINGTON DC 20310-0103
1	HQDA ATTN SARD TT DR F MILTON PENTAGON WASHINGTON DC 20310-0103
1	SDIO DA ATTN E GERRY PENTAGON WASHINGTON DC 21301-7100
1	SDIO TNI ATTN LH CAVENY PENTAGON WASHINGTON DC 21301-7100
1	EXPEDITIONARY WARFARE DIV N85 ATTN DR FRANK SHOUP 2000 NAVY PENTAGON WASHINGTON DC 20350-2000
1	CHAIRMAN DOD EXPLOSIVES SAFETY BD HOFFMAN BLDG 1 RM 856 C 2461 EISENHOWER AVE ALEXANDRIA VA 22331-0600
1	OFC OF THE PRODUCT MGR 155 MM HOWITZER M109A6 PALADIN ATTN SFAE AR HIP IP R DE KLEINE PCTNY ARSNL NJ 07806-5000
1	AFOSR NA ATTN J TISHKOFF BOLLING AFB DC 20332-6448
1	COMMANDANT ATTN AVIATION AGENCY US ARMY AVIATION SCHOOL FT RUCKER AL 36360

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	COMMANDANT ATTN REV AND TRNG LIT DIV US ARMY SPECIAL WARFARE SCH FT BRAGG NC 28307
1	COMMANDANT US ARMY CMND AND GEN STAFF COLLEGE FT LEAVENWORTH KS 66027
1	COMMANDER ATTN SMCWV QAE Q C HOWD BLDG 44 WATERVLIET ARSENAL WATERVLIET NY 12189-4050
1	COMMANDER ATTN SMCWV SPM T MCCLOSKEY BLDG 25 3 WATERVLIET ARSENAL WATERVLIET NY 12189-4050
1	COMMANDER ATTN SMCWV QA QS K INSCO WATERVLIET ARSENAL WATERVLIET NY 12189-4050
1	COMMANDER NASC ATTN AIR 954 TECH LIB WASH DC 20360
1	COMMANDER NAVAL SURFACE WARFARE CTR ATTN CODE R 13 R BERNECKER SLVR SPRNG MD 20903-5000
1	COMMANDER NAVAL SURFACE WARFARE CTR ATTN CODE E23 TECHNICAL LIBRARY DAHLGREN VA 22448-5000
1	COMMANDER NAVAL SURFACE WARFARE CTR ATTN S CULDER CODE 290D BLDG 600 INDIAN HEAD MD 20640-5000

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	COMMANDER NAVAL SURFACE WARFARE CTR ATTN CODE 730 SLVR SPRNG MD 20903-5000
3	COMMANDER NAVAL RESEARCH LAB ATTN CODE 4410 J BORIS K KAILASANATH E ORAN WASHINGTON DC 20375-5000
1	COMMANDER NAVAL SURFACE WARFARE CTR ATTN CODE G32 GUNS SYSTEMS DIVISION DAHLGREN VA 22448-5000
1	COMMANDER NAVAL SURFACE WARFARE CTR ATTN CODE G33 T DORAN DAHLGREN VA 22448-5000
1	COMMANDER NAVAL SURFACE WARFARE CTR ATTN CODE G30 GUNS & MUNITIONS DIVISION DAHLGREN VA 22448-5000
7	COMMANDER NAVAL SURFACE WARFARE CTR ATTN TC SMITH K RICE S MITCHELL S PETERS J CONSAGA C GOTZMER TECHNICAL LIBRARY INDIAN HEAD MD 20640-5000
1	COMMANDER NAVAL RESEARCH LAB ATTN TECH LIB WASH DC 20375-5000
1	COMMANDER NAWC ATTN INFORMATION SCI DIV CHINA LAKE CA 93555-6001

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
2	COMMANDER NAWC ATTN CODE 388 C PRICE T BOGGS CHINA LAKE CA 93555-6001
2	COMMANDER NAWC ATTN CODE 3895 T PARR R DERR CHINA LAKE CA 93555-6001
1	COMMANDER NSSC ATTN SEA 64 WASH DC 20362-5101
1	COMMANDER NSSC ATTN MR JOHN DELANY CODE 91WM ARLINGTON VA 22242-5160
1	COMMANDER NSSC ATTN SEA 62R WASH DC 20362-5101
1	COMMANDER NUSC ATTN CODE 5B331 TECHNICAL LIBRARY NEWPORT RI 02840
1	COMMANDER USACECOM R&D TECHNICAL LIBRARY ATTN ASQNC ELC IS L R MYER CTR FT MONMOUTH NJ 07703-5301
1	COMMANDER RADFORD ARMY AMMO PLANT ATTN SMCAR QA HI LIB RADFORD VA 24141-0298

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
3	COMMANDER US ARMY RESEARCH OFC ATTN TECH LIB D MANN K CLARK PO BOX 12211 RSCH TRI PK NC 27709-2211
1	COMMANDER US ARMY ARDEC ATTN SMCAR FSS A L PINDER PCTNY ARSNL NJ 07806-5000
2	COMMANDER US ARMY ARDEC ATTN SMCAR CCH V C MANDALA E FENNELL PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR FS DH J FENECK PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR FSA F LTC R RIDDLE PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR CCS PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR FSC G FERDINAND PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR FS T GORA PCTNY ARSNL NJ 07806-5000

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
12	COMMANDER US ARMY ARDEC ATTN SMCAR AEE B D DOWNS S EINSTEIN S WESTLEY S BERNSTEIN J RUTKOWSKI B BRODMAN P OREILLY R CIRINCIONE P HUI J OREILLY B STRAUSS J PREZELSKI PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR AEE J LANNON PCTNY ARSNL NJ 07806-5000
2	COMMANDER US ARMY ARDEC ATTN SMCAR FSS A R KOPMANN B MACHEK PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR AES S KAPLOWITZ PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR CCH T L ROSENDORF PCTNY ARSNL NJ 07806-5000
5	COMMANDER US ARMY ARDEC ATTN SMCAR AEE WW M MEZGER J PINTO D WIEGAND P LU C HU PCTNY ARSNL NJ 07806-5000

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	COMMANDER US ARMY ARDEC ATTN AMSMC PBM K PCTNY ARSNL NJ 07806-5000
5	COMMANDER US ARMY ARDEC ATTN SMCAR CCH T S MUSALLI P CHRISTIAN K FEHSAL N KRASNOW R CARR PCTNY ARSNL NJ 07806-5000
3	COMMANDER US ARMY ARDEC ATTN SMCAR TD R PRICE V LINDER T DAVIDSON PCTNY ARSNL NJ 07806-5000
2	COMMANDER US ARMY ARDEC ATTN SMCAR FSA M D DEMELLA F DIORIO PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN AMSMC PBE D FAIR PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR CCH V E FENNELL PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR CCH P J LUTZ PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR CCH J DELORENZO PCTNY ARSNL NJ 07806-5000

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	COMMANDER US ARMY ARDEC ATTN AMSMC PBM A SIKLOSI PROD BASE MODRNZTIN AGCY PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN AMSMC PBM E L LAIBSON PROD BASE MODRNZTIN AGCY PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR FSN N K CHUNG PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR HFM E BARRIERES PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN SMCAR FSE T GORA PCTNY ARSNL NJ 07806-5000
2	COMMANDER US ARMY ARDEC ATTN SMCAR CC J HEDDERICH COL SINCLAIR PCTNY ARSNL NJ 07806-5000
2	COMMANDER US ARMY ARDEC ATTN SMCAR FSA A WARNASH B MACHAK PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY ARDEC ATTN F MCLAUGHLIN PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY BELVOIR RD&E CTR ATTN STRBE WC FT BELVOIR VA 22060-5006

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>	<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	COMMANDER US ARMY BELVOIR RD&E CTR ATTN STRBE JBC FORT BELVOIR VA 22060-5606	1	PM TMAS ATTN SFAE AR TMA MD R KOWALSKI PCTNY ARSNL NJ 07806-5000
1	COMMANDER US ARMY NGIC ATTN AMXST MC 3 220 SEVENTH ST NE CHARLOTTESVILLE VA 22901-5396	1	PM AFAS ATTN SFAE ASM AF Q W WARREN PCTNY ARSNL NJ 07801-5000
1	COMMANDER USAMC ATTN AMCICP AD M FISETTE 5001 EISENHOWER AVE ALEXANDRIA VA 22333-0001	4	PM AFAS ATTN SFAE ASM AF E LTC A ELLIS T KURIATA G DELCOCO J SHIELDS PCTNY ARSNL NJ 07806-5000
1	PEO ARMAMENTS TMAS ATTN AMCPM TMA 105 PROJECT MANAGER PCTNY ARSNL NJ 07806-5000	2	PM TMAS ATTN SFAE AR TMA COL BREGARD C KIMKER PCTNY ARSNL NJ 07806-5000
1	PEO ARMAMENTS TMAS ATTN AMCPM TMA PROJECT MANAGER PCTNY ARSNL NJ 07806-5000	1	PROGRAM MANAGER US ARMY TACOM ATTN AMCPM ABMS T DEAN WARREN MI 48092-2498
1	PEO FAS ATTN SFAE FAS PM H GOLDMAN PCTNY ARSNL NJ 07806-5000	2	PROJECT MANAGER SADARM PCTNY ARSNL NJ 07806-5000
1	PEO ARMAMENTS TMAS ATTN AMCPM TMA AS H YUEN PROJECT MANAGER PCTNY ARSNL NJ 07806-5000	1	PROJECT MANAGER ATTN SFAE ASM BV US ARMY TACOM FIGHTING VEHICLE SYSTEMS WARREN MI 48397-5000
1	PEO ARMAMENTS TMAS ATTN AMCPM TMA 120 PROJECT MANAGER PCTNY ARSNL NJ 07806-5000	1	PROJECT MANAGER ATTN SFAE ASM AB ABRAMS TANK SYSTEM WARREN MI 48397-5000
2	PEO FAS ATTN SFAE FAS PM D ADAMS T MCWILLIAMS PCTNY ARSNL NJ 07806-5000	1	WL FIV A MAYER WRIGHT PATTERSON AFB DAYTON OH 45433
		1	WL MNAA ATTN B SIMPSON EGLIN AFB FL 32542-5434

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	WL MNME ENERGETIC MATERIALS BR 2306 PERIMETER RD STE 9 EGLIN AFB FL 32542-5910
1	WL MNSH ATTN R DRAB CZUK EGLIN AFB FL 32542-5434
1	DIRECTOR US ARMY TRAC FT LEE ATTN ATRC L MR CAMERON FT LEE VA 23801-6140
3	DIRECTOR BENET LABS ATTN SMCAR CCB RA G P O'HARA G A PFLEGL SMCAR CCB S F HEISER WATERVLIET NY 12189-4050
7	DIRECTOR BENET LABS ATTN AMSTA AR CCB C KITCHENS J KEANE J BATTAGLIA J VASILAKIS G FRIAR R HASENBEIN AMSTA AR CCB T S SOPOK WATERVLIET NY 12189-4050
1	DIRECTOR US ARMY RESEARCH LAB ATTN AMSRL MA P B HALPIN ARSNL STREET WATERTOWN MA 02172-0001
1	DIRECTOR US ARMY RESEARCH LAB ATTN AMSRL CP CA D SNIDER 2800 POWDER MILL ROAD ADELPHI MD 20783-1145
2	NASA LANGLEY RSRCH CTR ATTN AMSRL VS W ELBER AMSRL VS S F BARTLETT JR MAIL STOP 266 HAMPTON VA 23681-0001

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	DIRECTOR HQ TRAC RPD ATTN ATCD MA FT MONROE VA 23651-5143
1	DIRECTOR US ARMY CRREL ATTN P DUTTA 72 LYME ROAD HANOVER NH 03755
5	LAWRENCE LIVERMORE NATL LAB ATTN R CHRISTENSEN S DETERESA F MAGNESS M FINGER A HOLT PO BOX 808 LIVERMORE CA 94550
2	LAWRENCE LIVERMORE NATL LAB ATTN L 355 A BUCKINGHAM M FINGER PO BOX 808 LIVERMORE CA 94550-0622
1	LAWRENCE LIVERMORE NATL LAB ATTN M MURPHY PO BOX 808 L 282 LIVERMORE CA 94550
1	LOS ALAMOS NATL LAB ATTN J REPPA MS F668 PO BOX 1663 LOS ALAMOS NM 87545
1	LOS ALAMOS NATL LAB ATTN T3 D BUTLER PO BOX 1663 LOS ALAMOS NM 87544
1	LOS ALAMOS NATL LAB ATTN D RABERN MEE 13 MS J 576 PO BOX 1633 LOS ALAMOS NM 87545

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	LOS ALAMOS NATL LAB ATTN M DIV B CRAIG PO BOX 1663 LOS ALAMOS NM 87544
1	OAK RIDGE NATL LAB ATTN R M DAVIS PO BOX 2008 OAK RIDGE TN 37831-6195
1	SANDIA NATL LABS ENRGTC MATLS & FLUID MECH DEPARTMENT 1512 ATTN M BAER PO BOX 5800 ALBUQUERQUE NM 87185
1	SANDIA NATL LABS COMBUSTION RSCH FACILITY ATTN R CARLING LIVERMORE CA 94551-0469
1	SANDIA NATL LABS ATTN 8741 GA BENEDETTI PO BOX 969 LIVERMORE CA 94551-0969
5	SANDIA NATL LABS ATTN C ROBINSON W KAWAHARA K PERANO D DAWSON P NIELAN APLD MECH DEPT DIV 8241 PO BOX 969 LIVERMORE CA 94550-0096
2	HQ DNA ATTN D LEWIS A FAHEY 6801 TELEGRAPH RD ALEXANDRIA VA 22310-3398
4	INST FOR ADVNCD TECHNOLOGY ATTN W REINECKE T KIEHNE H FAIR P SULLIVAN 4030 2 W BRAKER LN AUSTIN TX 78759-5329

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	INST OF GAS TECHNOLOGY ATTN D GIDASPOW 3424 S STATE ST CHICAGO IL 60616-3896
1	NATL INST OF STANDARDS AND TECHNOLOGY STRUCTURE & MECHANICS GROUP POLYMER DIV POLYMERS RM A209 ATTN GREGORY MCKENNA GAITHERSBURG MD 20899
1	NAVAL ORDNANCE STATION ATTN D HOLMES CODE 2011 ADVANCED SYSTEMS TECHNOLOGY BR LOUISVILLE KY 40214-5245
2	NAVAL SURFACE WARFARE CTR DAHLGREN DIVISION ATTN CODE G33 DAHLGREN VA 224488
1	NAVAL SURFACE WARFARE CTR JOHN FRAYSSE ATTN CODE G33 DAHLGREN VA 22448
1	COMMANDER NAVAL SEA SYSTEMS CMD ATTN DAVID LIESE 2531 JEFFERSON DAVIS HIGHWAY ARLINGTON VA 22242-5160
1	NAVAL SURFACE WARFARE CTR ATTN CODE G30 JOSEPH H FRANCIS DAHLGREN VA 22448
1	NAVAL SURFACE WARFARE CTR ATTN MARY E LACY CODE D4 17320 DAHLGREN RD DAHLGREN VA 22448
1	OFFICE OF NAVAL TCHNLGY ATTN ONT 213 D SIEGEL 800 N QUINCY ST ARLINGTON VA 22217-5000

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	OFFICE OF NAVAL RESEARCH ATTN YAPA RAJAPAKSE MECH DIV CODE 1132SM ARLINGTON VA 22217
1	OFFICE OF NAVAL RESEARCH ATTN CODE 473 R S MILLER 800 N QUINCY ST ARLINGTON VA 22217-9999
1	OLAC PL TSTL ATTN D SHIPLETT EDWARDS AFB CA 93523-5000
3	OLAC PL RK ATTN J LEVINE L QUINN T EDWARDS 5 POLLUX DRIVE EDWARDS AFB CA 93524-7048
2	US ARMY RESEARCH OFFICE ATTN G ANDERSON R SINGLETON PO BOX 12211 RSRH TRI PK NC 27709-2211
2	US ARMY RESEARCH OFFICE ATTN ANDREW CROWSON J CHANDRA PO BOX 12211 RSRH TRI PK NC 27709-2211
1	US ARMY RD&S GROUP (UK) DR ROY E RICHENBACH PSC 802 BOX 15 FPO AE 09499-1500
1	USA BMD SYSTEMS COMMAND ADVANCED TECHNOLOGY CTR PO BOX 1500 HUNTSVILLE AL 35807-3801
1	RUTGERS UNIVERSITY DEPT OF MECHANICAL AND AEROSPACE ENGINEERING ATTN S TEMKIN UNIVERSITY HEIGHTS CAMPUS NEW BRUNSWICK NJ 08903

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	STANFORD UNIVERSITY DEPARTMENT OF AERONAUTICS AND AEROBALLISTICS DURANT BUILDING ATTN S TSAI STANFORD CA 94305
1	STEVENS INST OF TECH DAVIDSON LABORATORY ATTN R MCALEVY III CASTLE POINT STATION HOBOKEN NJ 07030-5907
1	STEVENS INST OF TCHNLGY HIGHLY FILLED MATERIALS INST ATTN DR DILHAN M KAYLON HOBOKEN NJ 07030
1	UCLA MANE DEPT ENGRG IV ATTN H THOMAS HAHN LOS ANGELES CA 90024-1597
2	UNIV OF ILLINOIS DEPT OF MECH INDUS ENGR ATTN H KRIER R BEDDINI 144 MEB 1206 N GREEN ST URBANA IL 61801-2978
1	UNIV OF MINNESOTA DEPT OF MECH ENGR ATTN E FLETCHER MINNEAPOLIS MN 55414-3368
1	UNIV OF MASSACHUSETTS DEPT OF MECH ENGR ATTN K JAKUS AMHERST MA 01002-0014
2	UNIV OF MINNESOTA AHPCRC ATTN G SELL D AUSTIN 1100 WASHINGTON AVE S MINNEAPOLIS MN 55415
3	UNIV OF DAYTON RESEARCH INST ATTN RAN Y KIM AJIT K ROY JAMES M WHITNEY 300 COLLEGE PARK AVENUE DAYTON OH 45469-0168

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
2	UNIV OF DELAWARE CTR FOR COMPOSITE MATERIALS ATTN J GILLESPE M SANTARE 201 SPENCER LABORATORY NEWARK DE 19716
1	UNIVERSITY OF UTAH DEPARTMENT OF MECHANICAL AND INDUSTRIAL ENGINEERING ATTN S SWANSON SALT LAKE CITY UT 84112
1	UNIVERSITY OF ILLINOIS AT URBANA CHAMPAIGN NATIONAL CENTER FOR COMPOSITE MATERIALS RESEARCH 216 TALBOT LABORATORY ATTN J ECONOMY 104 S WRIGHT STREET URBANA IL 61801
1	UNIVERSITY OF UTAH DEPT OF CHEM ENGNRG ATTN A BAER SALT LK CTY UT 84112-1194
1	UNIVERSITY OF KENTUCKY ATTN LYNN PENN 763 ANDERSON HALL LEXINGTON KY 40506-0046
1	WASHINGTON STATE UNIV DEPT OF MECH ENGNRG ATTN CT CROWE PULLMAN WA 99163-5201
1	BRIGHAM YOUNG UNIVERSITY DEPT OF CHEMICAL ENGNRNG ATTN M BECKSTEAD PROVO UT 84601
5	PENNSYLVANIA STATE UNIV DEPT OF MECH ENGNR ATTN V YANG K KUO W HSIEH S THYNELL C MERKLE UNIV PARK PA 16802-7501

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	PURDUE UNIVERSITY SCHOOL OF AERO & ASTRO ATTN C T SUN W LAFAYETTE IN 47907-1282
1	RENSSELAER POLYTECH INST ATTN R B PIPES PRESIDENT OFC PITTSBURGH BLDG TROY NY 12180-3590
1	RENSSELAER POLYTECH INST DEPT OF MATHEMATICS TROY NY 12181
1	CA INSTITUTE OF TECH 204 KARMAN LABORATORY MAIL STOP 301 46 ATTN F E C CULICK 1201 E CALIFORNIA ST PASADENA CA 91109
1	DREXEL UNIVERSITY ATTN ALBERT S D WANG 32ND AND CHESTNUT STS PHILADELPHIA PA 19104
3	GEORGIA INST OF TECH SCH OF AEROSPACE ENGRNG ATTN B T ZIM E PRICE WC STRAHLE ATLANTA GA 30332
1	CIA ATTN J BACKOFEN NHB ROOM 5N01 WASH DC 20505
1	CIA OFC OF INFO RESOURCES ROOM GA 07 HQS WASH DC 20505
1	3M SPECIALTY CHEMICALS ATTN A P MANZARA BLDG 70 2 10746 CHEMOLITE RD COTTAGE GROVE MN 55016

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
3	AAI CORPORATION ATTN TECH LIBRARY J FRANKLE D CLEVELAND PO BOX 126 HUNT VALLEY MD 21030-0126
1	AFELM THE RAND CORPORATION ATTN LIBRARY D 1700 MAIN ST SANTA MONICA CA 90401-3297
7	ALLIANT TECHSYSTEMS INC ATTN C CANDLAND J BODE R BECKER M SWENSON L OSGOOD R BURETTA T HOLMQUIST 600 2ND ST NE HOPKINS MN 55343-8367
2	ALLIANT TECHSYSTEMS INC ATTN R E TOMPKINS J KENNEDY 7225 NORTHLAND DR BROOKLYN PARK MN 55428
1	ARROW TECH ASSO 1233 SHELBURNE RD STE D 8 SOUTH BURLINGTON VT 05403-7700
7	CIVIL ENGR RESERACH FOUNDATION ATTN H BERNSTEIN PRESIDENT C MAGNELL K ALMOND R BELLE M WILLETT E DELO B MATTES 1015 15TH ST NW STE 600 WASHINGTON DC 20005
1	ARROW TECH ASSO INC ATTN W HATHAWAY PO BOX 4218 SOUTH BURLINGTON VT 05401-0042

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	BALLISTIC IMPACT DYNAMICS ATTN RODNEY RECHT 3650 S CHEROKEE 2 ENGLEWOOD CO 80110
1	VERITAY TECHNOLOGY INC ATTN E FISHER 4845 MILLERSPORT HWY EAST AMHERST NY 14501-0305
3	BATTELLE ATTN C R HARGREAVES TWSTIAC V LEVIN 505 KING AVE COLUMBUS OH 43201-2681
2	BATTELLE PNL ATTN M SMITH M C C BAMPTON PO BOX 999 RICHLAND WA 99352
1	BRIGS CO ATTN MR JOE BACKOFEN 2668 PETERBOROUGH ST HERDON VA 22071-2443
1	CHAMBERLAIN MFG CORP R&D DIV ATTN M TOWNSEND 550 ESTHER STREET WATERLOO IA 50704
1	DYNA EAST CORPORATION ATTN DR PEI CHI CHOU 3201 ARCH ST PHILADELPHIA PA 19104-2711
1	E I DU PONT DE NEMOURS & CO INC POTOMAC RIVER WORKS ATTN M MCGOWAN MARTINSBURG WV 25401
1	ELI FREEDMAN & ASSOC 2411 DIANA RD BALTIMORE MD 21209

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	COMPUTNL MECHANICS ASSOC ATTN JONAS A ZUKAS PO BOX 11314 BALTIMORE MD 21239-0314
2	CPIA JHU ATTN H J HOFFMAN T CHRISTIAN 10630 LTLE PATUXENT PKWY SUITE 202 COLUMBIA MD 21044-3200
1	CUSTOM ANALYTICAL ENGRNG SYSTEMS INC ATTN A ALEXANDER STAR ROUTE BOX 4A FLINTSTONE MD 21530
1	D R KENNEDY AND ASSOC INC ATTN D KENNEDY PO BOX 4003 MOUNTAIN VIEW CA 94040
1	DEFENSE NUCLEAR AGENCY INNOVATIVE CONCEPTS DIV ATTN DR R ROHR 6801 TELEGRAPH RD ALEXANDRIA VA 22310-3398
1	GEN DYNAMICS LAND SYS DIV ATTN D BARTLE PO BOX 1901 WARREN MI 48090
1	GENERAL ELECTRIC COMPANY TACTICAL SYSTEM DEPT ATTN J MANDZY 100 PLASTICS AVE PITTSFIELD MA 01201-3698
1	GENERAL APPLIED SCIENCES LAB ATTN J ERDOS 77 RAYNOR AVE RONKONKAMA NY 11779-6649
2	HERCULES INC ATTN D D WHITNEY E HAYS ZEIGLER 100 HOWARD BLVD KENVIL NJ 07847

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
2	HERCULES INC ALLEGHENY BALLISTICS LAB ATTN WILLIAM B WALKUP THOMAS F FARABAUGH PO BOX 210 ROCKET CENTER WV 26726
5	HERCULES INC RADFORD ARMY AMMO PLANT ATTN L GIZZI D WORRELL W WORRELL C CHANDLER F KRISTOFF RADFORD VA 24141-0299
1	HERCULES INC ATTN B M RIGGLEMAN HERCULES PLAZA WILMINGTON DE 19894
1	IITRI ATTN M J KLEIN 10 W 35TH ST CHICAGO IL 60616-3799
1	INTERFEROMETRICS INC ATTN R LARRIVA VP 8150 LESSBURG PIKE VIENNA VA 22100
1	JET PROPULSION LAB CA INSTITUTE OF TECH ATTN L STRAND MS 125 224 4800 OAK GROVE DRIVE PASADENA CA 91109
1	KAMAN SCIENCES CORP PO BOX 7463 COLORADO SPRINGS CO 80933
1	LIVERMORE SFTWR TECH CORP ATTN J O HALLQUIST 2876 WAVERLY WAY LIVERMORE CA 94550
2	LORAL VUGHT SYSTEMS ATTN G JACKSON K COOK 1701 W MARSHALL DR GRAND PRAIRIE TX 75051

NO. OF
COPIES ORGANIZATION

2 MARTIN MARIETTA CORP
ATTN P DEWAR
L SPONAR
230 EAST GODDARD BLVD
KING OF PRUSSIA PA 19406

1 MBR RESEARCH INC
ATTN DR MOSHE BEN REUVEN
601 EWING ST SUITE C22
PRINCETON NJ 08540

2 OLIN CORP
FLINCHBAUGH DIV
ATTN E STEINER
B STEWART
PO BOX 127
RED LION PA 17356

3 OLIN ORDNANCE
ATTN E J KIRSCHKE
A F GONZALEZ
D W WORTHINGTON
PO BOX 222
ST MARKS FL 32355-0222

1 OLIN CORP
ATTN L WHITMORE
10101 9TH ST NORTH
ST PETERSBURG FL 33702

1 OLIN CORPORATION
BADGER ARMY AMMO PLANT
ATTN F E WOLF
BARABOO WI 53913

1 PAUL GOUGH ASSOCIATES INC
ATTN P S GOUGH
1048 SOUTH ST
PORTSMOUTH NH 03801-5423

1 PHYSICS INTRNL LIBRARY
ATTN H WAYNE WAMPLER
PO BOX 5010
SAN LEANDRO CA 94577-0599

1 PM ADVANCED CONCEPTS
LORAL VOUGHT SYSTEMS
ATTN J TAYLOR
PO BOX 650003
MS WT 21
DALLAS TX 76265-0003

NO. OF
COPIES ORGANIZATION

2 PRINCETON CMBSTN RSCH LAB INC
ATTN N MER
N A MESSINA
PRINCETON CORPORATE PLAZA
11 DEERPARK DR BLDG IV STE 119
MONMOUTH JUNCTION NJ 08852

1 PROJECTILE TECHNOLOGY INC
515 GILES ST
HAVRE DE GRACE MD 21078

2 ROCKWELL INTERNATIONAL
ROCKETDYNE DIV
ATTN BA05 J FLANAGAN
WC79 R EDELMAN
6633 CANOGA AVE
CANOGA PARK CA 91303-2703

2 ROCKWELL INTRNL SCIENCE CTR
ATTN DR S CHAKRAVARTHY
DR S PALANISWAMY
PO BOX 1085
THOUSAND OAKS CA 91360

1 SAIC
ATTN DAN DAKIN
2200 POWELL ST STE 1090
EMERYVILLE CA 94608

1 SAIC
ATTN MILES PALMER
2109 AIR PARK RD S E
ALBUQUERQUE NM 87106

1 SAIC
ATTN ROBERT ACEBAL
1225 JOHNSON FERRY RD STE 100
MARIETTA GA 30068

1 SOUTHWEST RESEARCH INSTITUTE
ATTN MR JACK RIEGEL
ENGNRNG & MATERIAL SCIENCES DIV
PO DRAWER 28510
SAN ANTONIO TX 78228-0510

1 SRI INTERNATIONAL
PROPULSION SCIENCES DIV
ATTN TECH LIBRARY
333 RAVENWOOD AVE
MENLO PARK CA 94025-3493

NO. OF
COPIES ORGANIZATION

1 TEXTRON
 ATTN A PATRICK
 2385 REVERE BEACH PKWY
 EVERETT MA 02149-5900

1 THIOKOL CORPORATION
 ELKTON DIVISION
 ATTN TECH LIBRARY
 PO BOX 241
 ELKTON MD 21921-0241

1 THIOKOL COPORATION
 TACTICAL OPERATIONS
 ATTN W H OETJEN
 PO BOX 400006
 HUNTSVILLE AL 35815-106

1 THIOKOL CORPORATION
 ATTN DR DAVID A FLANIGAN
 PO BOX 707
 BRIGHAM CITY UT 84302-0707

2 UNITED DEFENSE LP
 ATTN P PARA
 G THOMAS
 1107 COLEMAN AVE BOX 367
 SAN JOSE CA 95103

1 UNIVERSIVAL PROPULSION CO
 ATTN H J MCSPADDEN
 25401 NORTH CENTRAL AVE
 PHOENIX AZ 85027-7837

1 JOHN HEBERT
 PO BOX 1072
 HUNT VALLEY MD 21030-0126

NO. OF
COPIES ORGANIZATION

ABERDEEN PROVING GROUND

1 CDR USAATC
 ATTN R HENDRICKSEN

68 DIR USARL
 ATTN AMSRL-SC,
 C MERMAGEN 394
 W STUREK 1121
 AMSRL-SC-S, A MARK 309
 AMSRL-SC-SS, R KASTE 394
 AMSRL-SL-B, P DIETZ 328
 AMSRL-SL-BA, J MORRISSEY 1065
 AMSRL-SL-BS, D BELY 328
 AMSRL-SL-I, D HASKILL 1065
 AMSRL-WT-P, A HORST 390A
 AMSRL-WT-PA,
 T MINOR 390
 C LEVERITT 390
 D KOOKER 390A
 AMSRL-WT-PB,
 E SCHMIDT 120
 P PLOSTINS 120
 AMSRL-WT-PC, R FIFER 390A
 AMSRL-WT-PD,
 B BURNS 390
 W DRYSDALE 390
 K BANNISTER 390
 T BOGETTI 390
 J BENDER 390
 R MURRAY 390
 R KIRKENDALL 390
 T ERLINE 390
 D HOPKINS 390
 S WILKERSON 390
 D HENRY 390
 R KASTE 390
 L BURTON 390
 J TZENG 390
 R LIEB 390
 G GAZONAS 390
 M LEADORE 390
 C HOPPEL 390
 AMSRL-WT-PD ALC,
 A ABRAHAMIAN
 K BARNES
 M BERMAN
 H DAVISON
 A FRYDMAN
 T LI
 W MCINTOSH
 E SZYMANSKI

NO. OF
COPIES ORGANIZATION

AMSRL-WT-T, W MORRISON 309
 AMSRL-WT-TA,
 W GILLICH 390
 W BRUCHEY 390
 AMSRL-WT-TB,
 F GREGORY 309
 AMSRL-WT-TC,
 K KIMSEY 309
 R COATES 309
 W DE ROSSET 309
 AMSRL-WT-TD,
 D DIETRICH 309
 G RANDERS PEHRSON 309
 J HUFFINGTON 309
 A DAS GUPTA 309
 J SANTIAGO 309
 AMSRL-WT-W, C MURPHY 120
 AMSRL-WT-WA,
 H ROGERS 394
 B MOORE 394
 AMSRL-WT-WB,
 F BRANDON 120
 W D'AMICO 120
 AMSRL-WT-WC, J ROCCHIO 120
 AMSRL-WT-WD,
 A NILLER 120
 A ZIELINSKI 120
 J POWELL 120
 AMSRL-WT-WE,
 J LACETERA 120
 J POWELL 120
 AMSRL-MA, L JOHNSON
 AMSRL-MA-PD, T CHOU
 AMSRL-MA, G HAGNAUER (CR)
 AMSRL-MA-PA, D GRANVILLE (CR)

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	DRA FORT HALSTEAD ATTN MR PETER N JONES W7 DIVISION BLDG A20 SEVENOAKS KENT TN 147BP ENGLAND
1	DRA FORT HALSTEAD ATTN DR D TOD RM 20, BLDG X50, ET5 SEVENOAKS KENT TN14 7BP ENGLAND
1	DRA FORT HALSTEAD ATTN DR DAVE SCOTT, TECH MGR LAUNCH SYSTEMS SEVENOAKS KENT TN14 7BP ENGLAND
3	DEFENSE RESEARCH ESTABLISHMENT- VALCARTIER ATTN MR FRANCOIS LESAGE DR S DUNCAN MR ALAIN DUPUIS PO BOX 8800 COURCELETTE, QUEBEC GOA 1RO CANADA
2	ROYAL MILITARY COLLEGE OF SCIENCE SHRIVENHAM ATTN DR DAVID BULMAN DR BRIAN LAWTON SWINDON, WILTS SN6 8LA UNITED KINGDOM
1	SWISS FEDERAL ARMAMENTS WORKS ATTN WALTER LANZ ALLMENDSTRASSE 86 3602 THUN SWITZERLAND
1	ISRAEL INSTITUTE OF TECHNOLOGY FACULTY OF MECHANICAL ENGINEERING ATTN PROFESSOR SOL BODNER HAIFA 3200 ISRAEL

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	DSTO MATERIALS RESEARCH LABORATORY DR NORBERT BURMAN NAVAL PLATFORM VULNERABILITY SHIP STRUCTURES AND MATERIALS DIV PO BOX 50 ASCOT VALE, VICTORIA AUSTRALIA 3032
1	ECOLE ROYAL MILITAIRE ATTN PROFESSPR EDWARD CELENS AVE DE LA RENAISSANCE 30 1040 BRUXELLE BELGIQUE
1	INSTITUT FRANCO-ALLEMAND DE RECHERCHES DE SANIT LOUIS ATTN DR CLAUDE FAUQUIGNON 5, RUE DU GENERAL CASSAGNOU BOITE POSTALE 34 F 68301 SAINT-LOUIS CEDEX FRANCE
1	INSTITUT FRANCO ALLEMAND DE RECHERCHES DE SANIT LOUIS ATTN DE MARC GIRAUD 5, RUE DU GENERAL CASSAGNOU BOITE POSTALE 34 F 68301 SAINT-LOUIS CEDEX FRANCE
1	TNO-PRINS MAURITS LABORATORY ATTN DR ROB IJSSELSTEIN LANGE KLEIWEG 137 PO BOX 45 2280 AA RIJSWIJK THE NETHERLANDS
1	FOA-NATIONAL DEFENSE RESEARCH ESTABLISHMENT ATTN DR BO JANZON DIRECTOR DEPT OF WEAPONS & PROTECTION S-172 90 STOCKHOLM SWEDEN
2	DEFENSE TECH & PROC AGENCY (GRD) ATTN MR GERHARD LAUBE GENERAL HERZOG HAUS 3602 THUN SWITZERLAND

<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>	<u>NO. OF COPIES</u>	<u>ORGANIZATION</u>
1	ROYAL MILITARY COLLEGE OF SCIENCE PROF J D MACKWORTH SHRIVENHAM SWINDON WILTS SN6 8LA UNITED KINGDOM	1	SCHOOL OF MECHANICAL, MATERIALS, AND CIVIL ENGINEERING ATTN DR BRYAN LAWTON ROYAL MILITARY COLLEGE OF SCIENCE SHRIVENHAM, SWINDON, WILSHIRE, SN6 8LA ENGLAND
1	MINISTRY OF DEFENCE RAFAEL ATTN DR MEIR MAYSELESS ARMAMENT DEVELOPMENT AUTHORITY PO BOX 2250 HAIFA 31021, ISRAEL	1	PRINS MAURTIS LABORATORIUM ATTN MR JAN MIEDEMA PO BOX 45 2280 AA RIJSWIJK ZH THE NETHERLANDS
1	DYNAMEC RESEARCH AB ATTN DR AKE PERSSON PARADISGRND 7 S 151 36 SODERTALJE SWEDEN	1	ESTABLISSEMENT TECHNIQUE DE BOURGES (ETBS) LPI (DIVISION LABORATOIRES MATEMIAUX PYROTECHNIQUES ET INERTES) BP n°712 ATTN MR ALAIN FABRE 18015 BOURGES CEDEX FRANCE
2	ERNST-MACH-INSTITUT (EMI) ATTN DR GUSTAV-ADOLF SCHRODER DR G ZIMMERMAN HAUPTSTRASSE 18 79576 WEIL AM RHEIN GERMANY	1	SNPE CENTRE DE RECHERCHES DU BOUCHET ATTN MR ROBERT NEVIÈRE BP2 91710 VERT-LE-PETIT FRANCE
1	ERNST-MACH-INSTITUT (EMI) ATTN DR ALOIS STILP ECKERSTRASSE 4 7800 FREIBURG GERMANY	2	INSTITUT SAINT LOUIS ATTN DR MARC GIRAUD DR GUNTER SHEETS POSTFACH 1260 7858 WEIL AM RHEIN 1 GERMANY
1	TNO-DEFENSE RESEARCH ATTN DR IR HANS PASMAN POSTBUS 6006 2600 JA DELFT THE NETHERLANDS	1	EXPLOSIVE ORDNANCE DIVISION ATTN A WILDEGGER-GAISSMAIER DEFENCE SCIENCE AND TECHNOLOGY ORGANIZATION PO BOX 1750 SALISBURY, SOUTH AUSTRALIA 5108
1	DR BITAN HIRSCH TACHKEMONY ST 6 NETANYA 42611 ISRAEL	1	BICT ATTN DR BURKHARD NICKLAS GROSSE CENT D-53913 SWISTTAL 1 GERMANY
1	DEUTSCHE AEROSPACE AG DYNAMIC SYSTEMS ATTN PROF DR MANFRED HELD PO BOX 1340 D-86523 SCHROBENHAUSEN GERMANY		

INTENTIONALLY LEFT BLANK.

USER EVALUATION SHEET/CHANGE OF ADDRESS

This Laboratory undertakes a continuing effort to improve the quality of the reports it publishes. Your comments/answers to the items/questions below will aid us in our efforts.

1. ARL Report Number ARL-TR-884 Date of Report October 1995

2. Date Report Received _____

3. Does this report satisfy a need? (Comment on purpose, related project, or other area of interest for which the report will be used.) _____

4. Specifically, how is the report being used? (Information source, design data, procedure, source of ideas, etc.) _____

5. Has the information in this report led to any quantitative savings as far as man-hours or dollars saved, operating costs avoided, or efficiencies achieved, etc? If so, please elaborate. _____

6. General Comments. What do you think should be changed to improve future reports? (Indicate changes to organization, technical content, format, etc.) _____

CURRENT
ADDRESS

Organization

Name

Street or P.O. Box No.

City, State, Zip Code

7. If indicating a Change of Address or Address Correction, please provide the Current or Correct address above and the Old or Incorrect address below.

OLD
ADDRESS

Organization

Name

Street or P.O. Box No.

City, State, Zip Code

(Remove this sheet, fold as indicated, tape closed, and mail.)
(DO NOT STAPLE)

DEPARTMENT OF THE ARMY

OFFICIAL BUSINESS

BUSINESS REPLY MAIL

FIRST CLASS PERMIT NO 0001,APG,MD

POSTAGE WILL BE PAID BY ADDRESSEE

DIRECTOR
U.S. ARMY RESEARCH LABORATORY
ATTN: AMSRL-WT-PD
ABERDEEN PROVING GROUND, MD 21005-5066



NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

